

Easybeader

1. Place the tool rest on centre height or slightly below as close to work as practically possible. The top cutting edge of the tool is now above centre when placed on the tool rest.
2. Slightly raise the handle so that the cutting edge is now on centre. Producing a trailing cut.
3. Slowly apply forward pressure so that the tool begins to cut.
4. A gentle side to side motion of the handle assists in removing the waste material.
5. Continue applying these actions until two perfect quarter circles have been produced.
6. If a row of beads is required, repeat stages 2-5 ensuring the shoulder of the tool is lined up with the outer edge of the previous quarter circle.
7. The Easybeader can also be used to create a perfect curved edge by using just one side. This is done by lining up the point of the tool with the face of the work and then following stages 1-5.
8. Sharpen the Easybeader using a diamond hone or flat oil stone across the top flat face.